



Request List for 111 Main St Hendersonville TN 37075

Last Modified: 2021-02-22 16:00:49

Roof Exterior

1. Awning Rail Trim (Curbside)








- Repair Requested
 - Customer Comment
 - Inspector's Comment
- 2.2 Most notable areas

1) Area approximately 13" from front cap

2) Two larger areas noted. One above front of awning and one above rear of awning.

It is recommended to have these inspected by a qualified RV technician.

2. Trim Rail (Streetside)



- **Repair Requested**
Customer Comment
- **Inspector's Comment**
2.4 Most notable areas


1) Area above rear slide out.

2) Above center slide out. In this area a soft spot approximately 1/2" in diameter was found in decking under rubber roof just above center streetside slideout along this edge.


It is recommended to have these inspected by a qualified RV technician.

Streetside Sidewall

3. Sidewall Condition



streetside wall above center slide out.



- **Repair Requested**
Customer Comment
- **Inspector's Comment**
3.0 C Inspector noted an area of delamination above the center slide out approximately . It is recommended to have this inspected by a qualified RV technician.

Curbside - Front Wheel Assembly

4. Tire Condition

- **Repair Requested**
Customer Comment
- **Inspector's Comment**
7.0 A Inspected noted tire pressure was 50 psi. Manufacturer recommends 65PSI. Recommend this be checked by a qualified technician

12 Volt DC Chassis Lights

5. Front Clearance Lights



- Repair Requested
Customer Comment
- Inspector's Comment
10.2 Front cap lights inoperable, clearance lights function properly

Propane Tank, Lines and Connections


6. DOT Tank(s)



- Repair Requested
Customer Comment
- Inspector's Comment
13.0 Inspector noted the tank certification on the on the streetside tank is expired. It is recommended that this be checked by a qualified technician.

Appliances: Other

7. Water Heater - Rubber Grommet Around Gas Line Sealed



- Repair Requested
Customer Comment
- Inspector's Comment
15.1 A hole in the sealer around the propane line feeding the water heater was noted. It is recommended to have this inspected by a qualified technician.